

Serial No. 10/705,324

IN THE SPECIFICATION

Page 1, lines 16-21 have been amended as follows:

2. When exposed to [[the]] sunshine for a long time, the clotheshorse made of plastic material will deform and become brittle whereby the ~~using useful~~ life of the clotheshorse is short. Thus, when not in use, the clotheshorse should be put in a room and shielded from sunlight. However, because it is difficult to detach the arms, the non-collapsed clotheshorse with a large overall size will occupy a great amount of space.

Page 4, line 23 through page 5, line 3 have been amended as follows:

With reference to Figs. 7-8, in another embodiment of the present invention, the arm ([[20']] 20a) has a ring (23) formed at the front end thereof. When two clotheshorses of the invention are mounted on the clothes-airing frame, a clothes bar ([[23]] 40) or a clothesline (not shown) can be attached between two opposed rings (23) of the two ~~clothes bar (23)~~ arms (20a) for hanging more clothes.

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER: _____**

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.